

N205SL

Date: 08/03/20
Time: 17:08:04

HÉLICRAFT 2000 INC.
Maintenance Tracking Report

Description: H-101 (REF 4H12) TCDS, 1 PAX, PISTON

Aircraft Tail Number: C-HILL

Last Flight: 07/02/26

Mfr.: SCHWEIZER, 1996 Model No.: 269 C-1

Serial No.: 0039

Hours: 5602.30

Cycles: 0

This Report is Ordered By: Time Remaining

ATA/Item Code	Item/Component Name	Part #	Serial #	Service Life	Airframe Times		Component Hours/Cycles		
					Installed/Completed At	Due At	Since New	At Installation	Remaining
M/R TRANSMISSION CARRIER	269A5175-023	S0629	8000RT	4200.00	8207.00	N/A	3993.00	2604.70	
M/R DRIVE SHAFT (SPLINED)	SA-269K-105-1	S0138/SZ0262	4000RT	4323.60	8323.60	N/A	0.00	2721.30	
BRG THRUST, M/R DIS	269A5050-063	4039	4200RT	4200.00	8400.00	N/A	0.00	2797.70	
TAILBOOM ASSY, PAINTED W	269A2320-015	S-0202	4200RT	4200.00	8400.00	N/A	0.00	2797.70	
HORIZ. STAB ASSY	269A2516-021	S-0595	4200RT	4200.00	8400.00	N/A	0.00	2797.70	
T/R TRANSMISSION	269A5600-703	S0087	4200OH	4200.00	8400.00	1402.30	0.00	2797.70	
T/R TRANSMISSION INPUT SHAFT	269A5600-703	S0087	8600RT	4200.00	8600.00	N/A	4200.00	2997.70	
T/R BLADE	269A6035-023	S2214	9000RT	3741.00	9000.00	N/A	3741.00	3397.70	
Comments: Inspection = every 600-HRS or 12 months, whichever occurs first. Service = 12-month NDT of T/R bushing holes per HMI.									
T/R BLADE	269A6035-023	S2225	9000RT	3741.00	9000.00	N/A	3741.00	3397.70	
Comments: Inspection = every 600-HRS or 12 months, whichever occurs first. Service = 12-month NDT of T/R bushing holes per HMI.									
STRAP ASSY, T/R ASSY	269A6065-507	S2184	5100RT	5100.70	10200.70	N/A	0.00	4598.40	
T/B SUPPORT STRUT	269A2015-015	S0037	10700RT	0.00	10700.00	N/A	0.00	5097.70	
T/B SUPPORT STRUT	269A2015-015	S0036	10700RT	0.00	10700.00	N/A	0.00	5097.70	
ELASTOMETRIC DAMPER, M/R	269A1290-3	8162	6000RT	4751.00	10751.00	N/A	0.00	5148.70	
Comments: PRIOR TO 4200 HRS COMPONENT TTSN = INSPECT EVERY 600 HOURS AFTER 4200 HRS TTSN - INSPECT EVERY 300 HRS									
ELASTOMETRIC DAMPER, M/R	269A1290-3	8193	6000RT	4751.00	10751.00	N/A	0.00	5148.70	
Comments: PRIOR TO 4200 HRS COMPONENT TTSN = INSPECT EVERY 600 HOURS AFTER 4200 HRS TTSN - INSPECT EVERY 300 HRS									
H2L-05 ELASTOMETRIC DAMPER, M/R	269A1290-3	8216	6000RT	4751.00	10751.00	N/A	0.00	5148.70	
Comments: PRIOR TO 4200 HRS COMPONENT TTSN = INSPECT EVERY 600 HOURS AFTER 4200 HRS TTSN - INSPECT EVERY 300 HRS									