

20552

Date: 08/03/20
Time: 17:08:04

HÉLICRAFT 2000 INC.
Maintenance Tracking Report
Description: H-101 (REF 4H12) TCDS, 1 PAX, PISTON

Aircraft Tail Number: C-FHLL
Mfr.: SCHWEIZER, 1996
Model No.: 269 C-1
Serial No.: 0039
Last Flight: 07/02/26
Hours: 5602.30
Cycles: 0

This Report is Ordered By: Time Remaining

AT/Item Code	Item/Component Name	Part #	Serial #	Service Life	Airframe Times		Component Hours/Cycles			
					Installed/Completed At	Due At	Since New Overhaul	At Installation Remaining		
	M/R SWASHPLATE BRG	269A1301		OC	3773.70	N/A	5602.30	N/A	3773.70	N/A
	T/R TRANSMISSION	269A5600-703	S0087	OC	0.00	N/A	5602.30	N/A	0.00	N/A
	T/R TRX, OUTPUT SHAFT	269A5106-003	S-426AGC	OC	5235.90	N/A	366.40	N/A	0.00	N/A
	SPARK PLUGS (3X)	REM38S		OC	0.00	N/A	5602.30	N/A	0.00	N/A
	T/R ASSY	269A6034-021	S2811	OC	5342.20	N/A	268.20	N/A	8.10	N/A
	BATTERY, GILL	G-243	G02255082	OC	5499.60	N/A	102.70	N/A	0.00	N/A
	SPARK PLUGS (5X)	REM38S		OC	5602.30	5702.30	N/A	N/A	N/A	100.00
Bulletin	AD 89-20-03R1	AD		100HR						
Bull. Description:	T/R BLADES									
	CF90-03 R2	CF		150HR	5602.30	5752.30	N/A	N/A	N/A	150.00
Bull. Description:	EXHAUST TYPE COCKPIT/CABIN HEATER (MUFF) INSPECTION OF PIPES & TUBES TO DETECT DETERIORATION.									
	AIR FILTER	BA5405		200RT	5602.30	5802.30	0.00	N/A	0.00	200.00
	M/R HUB AND SHAFT	SA-269K-105-1	S0138/SZ0262	200IN	5602.30	5802.30	0.00	N/A	0.00	200.00
Comments:	CHECK TORQUE OF M/R RETENTION NUT EVERY 200 HRS									
NOTE:	WHEN DISSASSEMBLED, CHECK TORQUE AT FIRST 10 HRS OF OPERATION.									
24-month INSP. =	INSPECT SHAFT FOR CORROSION, REF. BASIC HMI, section 10.									
SPECIAL INSPECTION:	REF. HMI, APP "B", Pg 2-31, # 22									
	M/R PITCH BEARING SHAFT	269A1240-007	S-4546	4000RT	3999.90	5832.70	3769.60	N/A	2167.20	230.40
	M/R PITCH BEARING SHAFT	269A1240-007	S-4554	4000RT	3999.90	5832.70	3769.60	N/A	2167.20	230.40
	ELASTOMETRIC DAMPER, M/R	269A1290-3	8162	600IN	5350.50	5950.50	851.30	N/A	0.00	348.20
Comments:	PRIOR TO 4200 HRS COMPONENT TTSN = INSPECT EVERY 600 HOURS AFTER 4200 HRS TTSN - INSPECT EVERY 300 HRS									
	ELASTOMETRIC DAMPER, M/R	269A1290-3	8193	600IN	5350.50	5950.50	851.30	N/A	0.00	348.20
Comments:	PRIOR TO 4200 HRS COMPONENT TTSN = INSPECT EVERY 600 HOURS AFTER 4200 HRS TTSN - INSPECT EVERY 300 HRS									
H21-05	ELASTOMETRIC DAMPER, M/R	269A1290-3	8216	600IN	5350.50	5950.50	851.30	N/A	0.00	348.20
Comments:	PRIOR TO 4200 HRS COMPONENT TTSN = INSPECT EVERY 600 HOURS AFTER 4200 HRS TTSN - INSPECT EVERY 300 HRS									