

N204SL

Date: 08/03/20
Time: 17:22:06

HÉLICRAFT 2000 INC.
Maintenance Tracking Report

Description: H-101 (REF. 4H12) TCDS

Aircraft Tail Number: C-GHNW

This Report is Ordered By: Time Remaining

ATA/Item Code	Item/POS	Component Name	Part #	Serial #	Service Life	Date Last Installed/Completed	Date To Be Removed/Completed	Action To Be Taken	Days To Go
		ANNUAL REPORT			12MO	2008/02/28	2009/02/28	Inspect	345
		COMPASS SWING			12MO	2008/03/17	2009/03/17	Inspect	362
		DUAL TACHOMETER	63-15	30276	12MO	2008/03/17	2009/03/17	Inspect	362
		T/R BLADE	269A6035-023	S2103	12MO	2008/03/18	2009/03/18	Inspect	363
		Comments: Inspection = every 600-HRS or 12 months, whichever occurs first. Service = 12-month NDT of T/R bushing holes per HMI.							
		T/R BLADE	269A6035-023	S2080	12MO	2008/03/19	2009/03/19	Inspect	364
		Comments: Inspection = every 600-HRS or 12 months, whichever occurs first. Service = 12-month NDT of T/R bushing holes per HMI.							
		OIL, M/R TRX	80W90		12MO	2008/03/19	2009/03/19	Retire	364
		OIL, T/R TRX	80W90		12MO	2008/03/19	2009/03/19	Retire	364
		Bulletin	CF90-03 R2	CF	365DY	2008/03/19	2009/03/19	Retire	364
		FIRE EXTINGUISHER	RT-A600	P022666	144MO	2008/12/31	2018/12/31	Retire	3938

Engine #1 Components

OIL, ENGINE	13W50, AEROSHELL	4MO	2008/03/19	Retire	121
-------------	------------------	-----	------------	--------	-----

Comments: (SB480E-OIL CHANGE IF NO FLIGHTS FOR 4 MONTHS) incorporated in Q-2092 p. 19 no.2 (25-hr) & p.22 lub.sys. (50-hr insp.)